

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/20/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S03M_026MH

Test ID: D1032-002010

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S03O__026MH
0			Start of Survey	
0			Water Level	
36.5	10		Tap Factory	From 4400 Frederick
36.5			Dye Test Visible	@ TF - downspout
36.5			End of Survey	DYE TEST COMPLETED ON THIS LINE
36.5			Manhole	S03M__012MH